WORK SURFACES USED IN RODENT PROCEDURES MUST BE EASILY DECONTAMINATED/SANITIZED OR COVERED BY IMPERVIOUS, DISPOSABLE DRAPES.

CORK BOARDS/STYROFOAM MAY ONLY BE USED FOR NECROPSY/NON-SURVIVAL PROCEDURES AND ONLY WHEN COVERED WITH A CLEAN, IMPERVIOUS, DISPOSABLE DRAPE

SC #162.1 Eff. 3/17